

June 10, 1977

Mr. Ron Osborn
2144 North Jefferson
Springfield, Missouri 65803

Dear Mr. Osborn:

In reference to the problem of sewage surfacing on your property, it appears to be caused by a break in the private sewer line coming from 2150 and 2156 North Jefferson which is attached to your private line. It appears that the owner or owners of 2144, 2150, and 2156 North Jefferson agreed at some point to connect their sewer lines together. It is the opinion of this office that the easiest way to correct this problem is through a joint effort from all three property owners. If an agreement is not reached between property owners, as to whose responsibility it is to repair this line, then this office will have to require that 2150 and 2156 North Jefferson attach to the City sanitary sewer line by a separate private line for each home.

If you have any questions, please feel free to call.

Yours truly,

Gene Pabst
Water Pollution Control Inspector III
Surveillance & Enforcement

GP:pg

cc: Mrs. Anne Little, 2150 North Jefferson
Rev. Leonard Cranor, 2156 North Jefferson
Mr. Robert Schaefer, Superintendent Sanitary Services
Mr. Steve Warner, City Health Department

2100 N. JEFFERSON